

**Professional Aviation Service**

Repair Station No. EASA IT.MF.0051
 Via Sabbionara 5
 40064 Ozzano Emilia (BO) Italy
 Phone: +39051795009
 Fax: +39051795009
 Email: info@professionalaviation.it
 VAT: IT 03657391201
 Date: 26/08/2020

CUSTOMER INFORMATION

Reg. No: I-FELC
 2008 CIRRUS SR22
 Current A/C TT: 633, FlightTime: 633
 A/C Serial: 22-3039

Customer Invoice
Work Order: 2689

Item: 1 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Airframe "100 hrs/Annual" inspection iaw Cirrus AMM SR22 P/N 13773-001 rev B8.	Flat	3.100,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Airframe "100 hrs/Annual" inspection iaw Cirrus AMM SR22 P/N 13773-001 rev B8.

Marco Gola: 0,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	MS17825-8	CASTELLATED NUT** (P/O: 2670) (Lot: CV 420/20; 244803) (Taxed)		22,06	22,06
1	EA	MS24665-285	PIN, COTTER CAD 3/32" X 1" (10) (P/O: 0518) (Lot: cv 116/12; 81045918) (Taxed)		0,45	0,45
1		MS24665-355	COTTER PIN** (5) (P/O: 0522) (Lot: cv 109/12; 81044036) (Taxed)		0,35	0,35
2		MS24665-360	PIN, COTTER CAD 1/8" X 2" ** (20) (P/O: 1159) (Taxed)		1,07	2,14

Labor: € 3.100,00	Parts: € 25,00	Shipping: € 0,00	Item Subtotal: € 3.125,00
--------------------------	-----------------------	-------------------------	----------------------------------

Item: 2 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Engine "100 hrs/Annual" inspection iaw Cirrus AMM SR22 P/N 13773-001 rev B8 and TCM MM M-16.	Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Engine "100 hrs/Annual" inspection iaw Cirrus AMM SR22 P/N 13773-001 rev B8 and TCM MM M-16.

Marco Gola: 0,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	CH48108-1	OIL FILTER** (P/O: 2716) (Lot: CV 480/20; 0007152708) (Taxed)		29,57	29,57
1	EA	MS29513-137	O-RING** (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)		6,00	6,00
1	EA	NAS1523-8B	STAT-O-SEAL** (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)		8,08	8,08
8	QT	W15W50	FUSTO OLIO MOTORE AEROSHELL W15W50** (P/O: 2674) (Lot: CV 426/20; 122/2020) (Taxed)		12,00	96,00

Labor: € 0,00	Parts: € 139,65	Shipping: € 0,00	Item Subtotal: € 139,65
----------------------	------------------------	-------------------------	--------------------------------

Item: 3 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Propeller "100 hr/Annual" Inspection and lubrications (Refer to Hartzell OM 115N rev 21)	Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Propeller "100 hr/Annual" Inspection and lubrications (Refer to Hartzell OM 115N rev 21)

 Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 4 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform List (22) SB SID SIL: TCM M90-17 Crankase Inspection Criteria, TCM MSB 94-8D Magneto to engine timing; TCM SB 95-2 Inspection and Maintenance of engine control cable; TCM SB96-7C Torque limit ; TCM 96-12 Continued Airworthiness instruction for TCM Cylinder; TCM SID 97-2B Maintenance and warranty for TCM cylinders; TCM SID 97-3G Procedures and specifications for adjustment of TCM continuous fuel injection system; TCM SIL 99-2C Current listing of sealant lubricant & adhesive authorized by TCM; TCM SB 03-3 Differential pressure test and borescope inspection; TCM SB 09-14 Crankshaft corrosion treatment; TCM SB 96-11B (PART II,C) system drain inspection ; TCM SB 95-7 Manifold valve cover inspection; TCM SB 97-6B Identify item to be replace during maintenance; TCM SIL 03-2C Currently Active Approved spark plug application; TCM SB 14-8 Exhaust Flange to Cylinder Installations; TCM SB15-1 Continental Motors Ignition Systems SB669 (Magneto Distributor Gear Block Inspection).	Flat	0,00

REQUESTED BY: CAMO Professional Aviation Service

Corrective Action

Performed List (22) SB SID SIL: TCM M90-17 Crankase Inspection Criteria, TCM MSB 94-8D Magneto to engine timing; TCM SB 95-2 Inspection and Maintenance of engine control cable; TCM SB96-7C Torque limit ; TCM 96-12 Continued Airworthiness instruction for TCM Cylinder; TCM SID 97-2B Maintenance and warranty for TCM cylinders; TCM SID 97-3G Procedures and specifications for adjustment of TCM continuous fuel injection system; TCM SIL 99-2C Current listing of sealant lubricant & adhesive authorized by TCM; TCM SB 03-3 Differential pressure test and borescope inspection; TCM SB 09-14 Crankshaft corrosion treatment; TCM SB 96-11B (PART II,C) system drain inspection ; TCM SB 95-7 Manifold valve cover inspection; TCM SB 97-6B Identify item to be replace during maintenance; TCM SIL 03-2C Currently Active Approved spark plug application; TCM SB 14-8 Exhaust Flange to Cylinder Installations; TCM SB15-1 Continental Motors Ignition Systems SB669 (Magneto Distributor Gear Block Inspection).

 Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 5 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Replace Induction Air Filter (refer to Cirrus AMM chap 71-60)	Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Replaced Induction Air Filter.

 Marco Gola: 0,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	50207-200	FILTER, ELEMENT BA-24 (P/O: 2628) (Lot: CV 385/2020; 242506) (Taxed)		26,20	26,20

Labor: € 0,00	Parts: € 26,20	Shipping: € 0,00	Item Subtotal: € 26,20
----------------------	-----------------------	-------------------------	-------------------------------

Item: 6 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Fuel Injection System Functional inspection; remove and clean fuel injection nozzles, iaw TCM M-0 Chg 5 (Ref. to Chpt 6.4.7)	Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Fuel Injection System Functional inspection; removed and cleaned fuel injection nozzles, iaw TCM M-0 Chg 5.

 Giovanni Panicali: 0,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
6	EA	628556	WASHER, TELEDYNE (P/O: 2709) (Lot: CV 473/20; 303/2020) (Taxed)		1,41	8,46
6	EA	630979-9	O-RING SEAL, TELEDYNE (MINIMUM ORDER QTY 50)** (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)		7,41	44,46
6	EA	640612	WASHER, RUBBER TELEDYNE** (P/O: 2765) (Lot: CV 520/20; 431/2020) (Taxed)		1,74	10,44
6	EA	X1473	WASHER, COPPER TELEDYNE (P/O: 2739) (Lot: CV 500/20; 250595) (Taxed)		2,85	17,10

Labor: € 0,00	Parts: € 80,46	Shipping: € 0,00	Item Subtotal: € 80,46
----------------------	-----------------------	-------------------------	-------------------------------

Item: 7 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Oil Analysis	Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Oil sample taken and sent out for analysis.

 Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 8 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform FAA SAIB CE-04-22 - Exhaust system components inspection	Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed FAA SAIB CE-04-22 - Exhaust system components inspection.

 Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 9 - Airworthy Airframe

Discrepancy

Perform Oil and Oil Filter Change. Drain and change engine oil, check for metal particles or foreign material on sump drain plug. Replace oil Filter: inspect filter element for metal particles. (Ref. Cirrus AMM Ch. 12-10, TCM MM and SIL 99-2C).

Hours	Subtotal
Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Oil and Oil Filter Change. Drained and changed engine oil, checked for metal particles or foreign material on sump drain plug. Replaced oil Filter: inspected filter element for metal particles.

Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 10 - Airworthy Airframe

Discrepancy

Perform Capacity Test of Concorde Battery (refer to Cirrus AMM Chap 24-30).

Hours	Subtotal
Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Capacity Test of Concorde Battery, Test Pass, result 99%.

Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 11 - Airworthy Airframe

Discrepancy

Perform ELT Operational Test (Refer to Artex MM p/n 570-1600).

Hours	Subtotal
Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed ELT Operational Test.

Davide Mengozzi: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 12 - Airworthy Airframe

Discrepancy

Perform Detail Visual Inspection of Seat Belts and Shoulder Harness.

Hours	Subtotal
Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Detail Visual Inspection of Seat Belts and Shoulder Harness.

Davide Mengozzi: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 13 - Airworthy Airframe

Discrepancy

Perform Hartzell HC-SL-61-185/1- Accuracy test Tachometer

Hours	Subtotal
Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Hartzell HC-SL-61-185/1- Accuracy test Tachometer

Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 14 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform First Aid Kit inspection	Flat	0,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed First Aid Kit inspection

Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Item: 15 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Ice Protection in-line Strainer servicing (refer Cirrus AMM chap 30-06 Basic, 30-07 FIKI)	1,00	75,00

Requested by CAMO Professional Aviation Service

Corrective Action

Performed Ice Protection in-line Strainer servicing.

Andrea Ascione: 1,00

Marco Gola: 0,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	AS3582-112	O-RING 9/16 (P/O: 1975) (Lot: CV 15/18 ; SCCS4) (Taxed)		0,81	0,81

Labor: € 75,00	Parts: € 0,81	Shipping: € 0,00	Item Subtotal: € 75,81
-----------------------	----------------------	-------------------------	-------------------------------

Item: 16 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Replace TKS filter	1,00	75,00

Requested by CAMO Professional Aviation Service

Corrective Action

Replaced TKS filter

Andrea Ascione: 1,00

Marco Gola: 0,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
2	EA	15164-092B	SEALING RING 5/16 S1201-20** (5) (P/O: 2418) (Lot: CV 160/19; CDC 052019-012) (Taxed)		6,70	13,40
2	EA	15164-093	SEAL RING 3/8 100-011-8810 (P/O: 2307) (Lot: CV 060/19; CDC 021319-009) (Taxed)		10,86	21,72
1	EA	26115-101	FILTER ELEMENT, TKS DE-ICE SYSTEM** (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)		430,00	430,00

Labor: € 75,00	Parts: € 465,12	Shipping: € 0,00	Item Subtotal: € 540,12
-----------------------	------------------------	-------------------------	--------------------------------

Item: 17 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform alternator#1 2yrs /500 hrs inspection	2,00	150,00

Corrective Action

Replaced alternator#1.Removed P/N ES-10024 & S/N H091236. Installed P/N ES-10024 & S/N H-P010890.

 Marco Gola: 2,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	ES-10024-INSP	24 Vlt 100 Amp Alternator (P/O: 2718) (Lot: CV 494/20; 2020120) (Taxed)	H-P010890	257,25	257,25

Labor: € 150,00	Parts: € 257,25	Shipping: € 0,00	Item Subtotal: € 407,25
------------------------	------------------------	-------------------------	--------------------------------

Item: 18 - Airworthy Airframe

Discrepancy	Hours	Subtotal
ARC Estensione	Flat	180,00

Corrective Action

ARC Estensione

Labor: € 180,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 180,00
------------------------	----------------------	-------------------------	--------------------------------

Item: 19 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Replace Battery #2.	1,50	112,50

Corrective Action

Replaced Battery #2.

 Andrea Ascione: 1,50
 Marco Gola: 0,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
2	EA	21063-001	BATTERY, SEALED LEAD ACID** (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)		104,85	209,70

Labor: € 112,50	Parts: € 209,70	Shipping: € 0,00	Item Subtotal: € 322,20
------------------------	------------------------	-------------------------	--------------------------------

Item: 20 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Replace CAPS Reefing line cutters	1,00	75,00

Corrective Action

Replace CAPS Reefing line cutters.Removed P/N 25347-002 & S/N 5852 / 5861. Installed P/N 25347-002 & S/N 15847 - 15841.

 Marco Gola: 1,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	25347-002	KIT, LINE CUTTER REPLACEMENT, SR20/22 (P/O: 2678) (Lot: CV 424/20; 241404) (Taxed)	15847-15841	1.795,85	1.795,85

Labor: € 75,00	Parts: € 1.795,85	Shipping: € 0,00	Item Subtotal: € 1.870,85
-----------------------	--------------------------	-------------------------	----------------------------------

Item: 21 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Compass Calibration & Mag calibration	0,50	37,50

Corrective Action

Performed Compass Calibration & Mag Calibration

 Marco Gola: 0,50

Labor: € 37,50	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 37,50
-----------------------	----------------------	-------------------------	-------------------------------

Item: 22 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Replace Pilot & Co-pilot seat inflator.	2,50	187,50

Corrective Action

Replace Pilot & Co-pilot seat inflator. Removed Co-pilot P/N 20902-002 & S/N AASI 023V 10572. Installed Co-pilot P/N 20902-005 & S/N Z7EE232D0273. Removed Pilot P/N 20902-002 & S/N AASI 023V 10572. Installed Pilot P/N 20902-005 & S/N Z7EE231D0676.

 Davide Mengozzi: 2,50

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	20902-005	INFLATOR, AAIR (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)	Z7EE232D0273	330,16	330,16
1	EA	20902-005	INFLATOR, AAIR (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)	Z7EE231D0676	330,16	330,16
2	EA	20902-006	WIRE HARNESS, SEAT, AAIR (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)		304,76	609,52
2	EA	20902-007	FITTING Inflator To Hose Adapter (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)		73,82	147,64
8	EA	20903-008	BRACKET, INFLATOR, AAIR (P/O: 2722) (Lot: CV 486/20; 250104) (Taxed)		22,29	178,32
2		50132-001	HOLDER, TIE DOWN RESTRAINT, EMS-A-DO (10) (P/O: 2456) (Lot: CV 218/19; 230803) (Taxed)		3,81	7,62

Labor: € 187,50	Parts: € 1.603,42	Shipping: € 0,00	Item Subtotal: € 1.790,92
------------------------	--------------------------	-------------------------	----------------------------------

Item: 23 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Replace ELT Battery	0,50	37,50

Corrective Action

Replaced ELT Battery, New exp date 30 August 2027.

 Davide Mengozzi: 0,50

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	455-0012	ME406, 452.6504, BARR PCK, RPLC (P/O: 2779) (Lot: CV 533/20; P151171) (Taxed)	387209-023	212,00	212,00

Labor: € 37,50	Parts: € 212,00	Shipping: € 0,00	Item Subtotal: € 249,50
-----------------------	------------------------	-------------------------	--------------------------------

Item: 24 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Engine 12 yrs Inspection.	24,00	1.800,00

Corrective Action

Performed Engine 12 yrs Inspection.

 Marco Gola: 24,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	124J001-4CR-0070	HOSE ASSY 124.04.GG-0195 (P/O: 2775) (Lot: CV 516/20; SL20-545M) (Taxed)	SL20-545M-1	171,53	171,53
1	EA	124J002-4CR-0140	HOSE ASSY 124.04.J.G90-0365 (P/O: 2775) (Lot: CV 516/20; SL20-545M) (Taxed)	SL20-545M-3	232,29	232,29
1	EA	124J003-4CR-0105	HOSES ASSY 124.04.J.G45-0280 (P/O: 2775) (Lot: CV 516/20; SL20-545M) (Taxed)	SL20-545M-2	238,91	238,91
12		501868	WASHER - ROCKER ARM LOCK TAB** (P/O: 2739) (Lot: CV 500/20; 250595) (Taxed)		2,24	26,88
11		501868	WASHER - ROCKER ARM LOCK TAB** (P/O: 2453) (Lot: CV 200/19; 230331) (Taxed)		2,24	24,64
1		501868	WASHER - ROCKER ARM LOCK TAB** (P/O: 2432) (Lot: CV 180/19; 229119) (Taxed)		2,24	2,24
10		534610	PACKING-PUSH ROD HOUSING TCM (P/O: 2397) (Lot: CV 164/19; 543908) (Taxed)		1,68	16,80
2		534610	PACKING-PUSH ROD HOUSING TCM (P/O: 2578) (Lot: CV 339/19; 238237) (Taxed)		1,68	3,36
8		630286	SEAL- ""O"" RING (P/O: 0354) (Lot: 80968775) (Taxed)		4,30	34,40
4		630286	SEAL- ""O"" RING (P/O: 2432) (Lot: CV 187/19; 229119) (Taxed)		5,59	22,36
1	EA	646433-9A4	FUEL DIVIDER TCM (P/O: 2761) (Lot: CV 553/20; S-ZER113945) (Taxed)	C08CA211	625,00	625,00
3		649950	INTAKE MANIFOLD GASKET IO-550-N (P/O: 1995) (Lot: CV 37/18 ; 498692) (Taxed)		4,07	12,21
1		652094	GASKET, THROTTLE BODY TELEDYNE** (P/O: 0182) (Lot: cv 56/10; 80798073) (Taxed)		5,97	5,97
1	EA	653353-8A1-OH-E	THROTTLE & CONTRL ASSY WITH HOSES, SUPERCEDED TO 653353 (P/O: 1793) (Lot: cv 114/17; 026597) (Taxed)	A07LA035	382,56	382,56
1	EA	AE7010001G0080	TUBAZIONE MOTORE TCM (P/O: 2767) (Lot: CV 532/2020; 2767) (Taxed)	-	131,07	131,07
1	EA	AE7010201H0125	TUBAZIONE MOTORE TCM (P/O: 2767) (Lot: CV 532/2020; 2767) (Taxed)	-	131,07	131,07
1	EA	AE7010201H0137	TUBAZIONE MOTORE TCM (P/O: 2767) (Taxed)	-	131,68	131,68
12	EA	SA632459	GASKET ROCKER COVER alternative.: 655705 (P/O: 2709) (Lot: CV 473/20; 303/2020) (Taxed)		1,90	22,80

Labor: € 1.800,00	Parts: € 2.215,77	Shipping: € 0,00	Item Subtotal: € 4.015,77
--------------------------	--------------------------	-------------------------	----------------------------------

Item: 25 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Replace magnetos for overhaul	3,00	225,00

Corrective Action

Replaced magnetos for overhaul. Removed LH Magneto P/N 10-500556-1 & S/N D07GA050. Installed LH Magneto 10-500556-1 & S/N D16BA036. Removed RH Magneto 10-500556-1 & S/N A284259 Installed RH Magneto P/N 10-500556-1 & S/N D16BA027.

 Davide Mengozzi: 3,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		10-500556-1-OH-E	MAGNETO, IO550 (P/O: 2587) (Lot: CV 370/19; 2019302) (Taxed)	D16BA036	980,00	980,00
1		10-500556-1-OH-E	MAGNETO, IO550 (P/O: 2587) (Lot: CV 370/19; 2019302) (Taxed)	D16BA027	980,00	980,00
2		649954	MAGNETO GASKET SUPERCEDED TO 10-400613 (P/O: 2432) (Lot: CV 180/19; 229119) (Taxed)		2,22	4,44

Labor: € 225,00	Parts: € 1.964,44	Shipping: € 0,00	Item Subtotal: € 2.189,44
------------------------	--------------------------	-------------------------	----------------------------------

Item: 26 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Replace fire extinguisher for life limit	0,00	0,00

Corrective Action

Replaced fire extinguisher.

 Andrea Ascione: 0,00
 Marco Gola: 0,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1		12533-004	EXTINGUISHER, FIRE H3R HALON RT (supersed 12533-003) (P/O: 2739) (Lot: CV 500/20; 250595) (Taxed)	G-01223160	176,19	176,19

Labor: € 0,00	Parts: € 176,19	Shipping: € 0,00	Item Subtotal: € 176,19
----------------------	------------------------	-------------------------	--------------------------------

Item: 27 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Propeller overhaul	2,00	150,00

Corrective Action

Performed Propeller overhaul.

 Marco Gola: 2,00

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	PHC-J3YF-1RF-OSR	HARTZELL ALLUMINIUM PROPELLER (P/O: 2750) (Lot: CV 517/20; 20200625A) (Taxed)	FP3619B	3.519,00	3.519,00

Labor: € 150,00	Parts: € 3.519,00	Shipping: € 0,00	Item Subtotal: € 3.669,00
------------------------	--------------------------	-------------------------	----------------------------------

Item: 28 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform Avionic Ramp test	Flat	650,00

Corrective Action

Performed Avionic Ramp test, see wo #2742

Labor: € 650,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 650,00
------------------------	----------------------	-------------------------	--------------------------------

Item: 29 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Perform SB 2X-71-33. Release of TCM service document SB 18-08	0,00	0,00

Corrective Action

Performed SB 2X-71-33. Release of TCM service document SB 18-08

Marco Gola: 0,00

Labor: € 0,00	Parts: € 0,00	Shipping: € 0,00	Item Subtotal: € 0,00
----------------------	----------------------	-------------------------	------------------------------

Additional Charges							Subtotal
Pilot Services	Tire Disposal	EPA Charge	Oil Analysis	Shop Supplies	Fuel	Misc.	
0,00	0,00	0,00	60,00	0,00	0,00	0,00	€ 60,00

Labor Summary	
Shop Labor: € 6.855,00	Outside Repair: € 0,00

Total Labor:	€ 6.855,00
Total Parts:	€ 12.690,86
Total Shipping:	€ 0,00
Additional Charges:	€ 60,00
VAT:	€ 4.313,29
Amount Due:	€ 23.919,15
Deposit:	€ 0,00
Balance Due:	€ 23.919,15

Taxed Items:

EPA Charge, Fuel, Shop Labor, OSR Labor, Misc. Charges, Oil Analysis, Shop Parts, OSR Parts, , Shipping In, Shipping Out, Shop Supplies, Tire Disposal

Tax Breakdown: (Before Calculated)

EPA Charge: 0,00
 Fuel: 0,00
 Shop Labor: 6.855,00
 OSR Labor: 0,00
 Misc. Charges: 0,00
 Oil Analysis: 60,00
 Shop Parts: 12.690,86
 OSR Parts: 0,00
 : 0,00
 Shipping In: 0,00
 Shipping Out: 0,00
 Shop Supplies: 0,00
 Tire Disposal: 0,00

Technician Summary:

Andrea Ascione: 3.5
 Davide Mengozzi: 6
 Giovanni Panicali: 0
 Marco Gola: 29.5

Important Information

Rossello Fabio or Authorized Representative

Date